Oil Field Environmental Incident Summary

Responsible Party: WPX ENERGY WILLISTON, LLC **Well Operator:** WPX ENERGY WILLISTON, LLC

Well Name: MANDAREE 30-31H

Field Name: REUNION BAY Well File #: 19603

Date Incident:1/18/2015Time Incident:11:22Facility ID Number:County:DUNNTwp:150Rng:93Sec:30Qtr:

Location Description:

Submitted By: Jim Raley Received By:

Contact Person: Jim Raley

1001 17TH STREET, SUITE 1200

DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 5 Barrels 5 Barrels 5 barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/29/2015 Clean Up Concluded: 3/1/2015

Risk Evaluation:No immediate risk.

Areal Extent:

Potential Environmental Impacts:

No water was impacted or threatened to be impacted. No equipment was damaged and no personal injury occurred as a result of this incident. Impacts are limited to soils on location.

Action Taken or Planned:

Piping connection will be repaired. Liquids will be removed and properly disposed.

Wastes Disposal Location: Prairie Disposal

Agencies Involved: MHA, BIA

Updates

Date: 1/20/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill occurred within the MHA Nation boundaries. Forward to BIA/Tribal authorities.